

FRONTIER HARD CHROME SITE INSPECTION PHOTOS

November 2017 (WA Dept Ecology)

Photo 1: West Side of the New Building and Employee Parking Lot – From Northwest (from “Y” Street)



Photo 2: West Side of the New Building – From Southwest (from East 1st Street)



Photo 3: New Building and Employee Parking Lot – From North



Photo 4: New Building and the East 1st Street – From Southeast (from Fred Myer Parking Lot)



Photo 5: Existing Office Building and Eastern Portion of the Site – From Northeast



Photo 6: New Building and Eastern Portion of the Site, Future Storage Area – From the East



Photo 7: Eastern Portion of the Site and the Existing Office Building – From the North



Photo 8: New Building and Eastern Portion of the Site, Future Storage Area – From the East



Photo 9: Connecting Corridor, New Building and the Existing Office Building–From the North



Photo 10: Construction of Bioretention Area next to the “Y” Street – From the North



Photo 11: Construction of Bioretention Area next to the “Y” Street – From the West



Photo 12: Construction In-side the New Building – From the South



Photo 13: Construction In-side the New Building – From the Northeast



Photo 14: Construction In-side the New Building – From the North



Photo 15: Construction In-side the New Building – From the West



Photo 16: Groundwater Monitoring Wells W85-6A and W85-6B identified for decommissioning



Photo 17: Groundwater Monitoring Wells W85-5A and W85-5B identified for decommissioning



Photo 18: Groundwater Monitoring Well W98-21A & B identified for decommissioning next to

Highway-14